



LANSING

Dining table 1400




CONNECT SYSTEM

1




2



(Connecting bolts)

3



WHEN FITTING CAMS
ENSURE STARTING POSITION IS CORRECT
BEFORE YOU INSERT CONNECTING BOLT
TURN CLOCKWISE UNTIL SECURE

✓



↑

CORRECT










WRONG

✗

HARDWARE



x 4




x 2



x 2



x 12



x 8



x 6



x 1



x 2




x 12








x 12

PART




1.




	x4		x2		x2
--	-----------	--	-----------	--	-----------


2.



3.




4.



M6 x 35		X8
		X1

5.



	X2
---	-----------